

Hoarding and Perimeter Inspections

JAJ GROUP LTD

Contract Name	30 – 32 Staines Road, Hounslow	Person Carrying out the Inspection	Bes Beqa
Date of Inspection	09 / 09 / 2019	Time of Inspection	09.00

Element inspected	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
Hoarding Support: <ul style="list-style-type: none"> Posts vertical Posts / kentledge secure Undermining 	The Main Entrance Door & Hoarding is safe, Secured and in good Condition.	<i>Bes Beqa</i>	No Action Required
Hoarding Panels: <ul style="list-style-type: none"> Securely fixed to posts / rails No nails protruding Skirting / capping secure Clean / check for graffiti 	The Main Entrance Door & Hoarding is safe, Secured and in good Condition.	<i>Bes Beqa</i>	No Action Required
Viewing Panels: <ul style="list-style-type: none"> Clean Safe View portrays a good image 	No Viewing Panels present at this time.	<i>Bes Beqa</i>	No Action Required
Doors and openings: <ul style="list-style-type: none"> Working order Locks ok Clean 	All Doors and Locks are clean, safe and in good working order.	<i>Bes Beqa</i>	No Action Required
Lighting: <ul style="list-style-type: none"> Bulbs Casings Guards 	No Lighting installed on Front & Rear side of the hoarding as its not required.	<i>Bes Beqa</i>	No Action Required
Pedestrians: <ul style="list-style-type: none"> Pavements clean Check for Trip hazards Signage clean 	The Signage & Pavement is clean and clear and there are no hazards to the Public and to Site Staff.	<i>Bes Beqa</i>	No Action Required
Heras Fencing: <ul style="list-style-type: none"> Ground level / firm Blocks 90° to panels Couplers – 2 per joint Bracing if required Panels damage free Securely fixed at ends 	The Heras Fencing is safe and secured with Double Clips, Rubber Feet and secured to the building with Rope on front side of the building.	<i>Bes Beqa</i>	No Action Required