

## Working Platforms, Fall Prevention, Arrest Systems and Ladder Inspection

The Work at Height Regulations 2005	
Report of result of inspection (Regulation 12 (4)(a)(b)) of WORKING PLATFORMS (or part thereof) or of other FALL PREVENTION & ARREST SYSTEMS (including equipment and materials, if any) or of LADDERS as required by Regulation 12 of the Work at Height Regulations	
Note:	1. Where necessary the manufacturer's instruction or other available information should be consulted. 2. Inspection periods must not exceed 7 days 3. Company owned, hired and equipment belonging to employees / subcontractors must be recorded on this form.

<b>Contract Name</b>	30 – 32 Staines Road, Hounslow	<b>Person Carrying out the Inspection</b>	Bes Beqa
<b>Date of Inspection</b>	21 / 10 / 2019	<b>Time of Inspection</b>	09.00

Location and Description of Equipment	Unique Reference Number	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
Orange Step Ladder – 1.45 Mtr Long	THME A10	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 2.3 Mtr Long	THME A04	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 2.25 Mtr Long	THME K56	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Step Ladder – 1.7 Mtr Long	A 07	Good Working Order	<i>Bes Beqa</i>	No Action Required
Orange Step Ladder – 1.7 Mtr Long	A 08	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 2.15 Mtr Long	K 119	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.15 Mtr Long	Bruka A01	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Step Ladder – 1.8 Mtr Long	JAJ A04	Good Working Order	<i>Bes Beqa</i>	No Action Required
Blue Step Ladder – 1.7 Mtr Long	09 / 1292 / No198	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.7 Mtr Long	K 55	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.7 Mtr Long	THME 032	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.7 Mtr Long	THME 033	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.7 Mtr Long	THME 034	Good Working Order	<i>Bes Beqa</i>	No Action Required

## Working Platforms, Fall Prevention, Arrest Systems and Ladder Inspection

The Work at Height Regulations 2005	
Report of result of inspection (Regulation 12 (4)(a)(b)) of WORKING PLATFORMS (or part thereof) or of other FALL PREVENTION & ARREST SYSTEMS (including equipment and materials, if any) or of LADDERS as required by Regulation 12 of the Work at Height Regulations	
Note:	1. Where necessary the manufacturer's instruction or other available information should be consulted. 2. Inspection periods must not exceed 7 days 3. Company owned, hired and equipment belonging to employees / subcontractors must be recorded on this form.

<b>Contract Name</b>	30 – 32 Staines Road, Hounslow	<b>Person Carrying out the Inspection</b>	Bes Beqa
<b>Date of Inspection</b>	21 / 10 / 2019	<b>Time of Inspection</b>	09.00

Location and Description of Equipment	Unique Reference Number	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
Silver Step Ladder – 2 Mtr Long	Bruka A03	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 1.15 Mtr Long	Bruka A02	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 3.10 Mtr Long	THME 108	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 2.0 Mtr Long	THME 107	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Step Ladder – 1.9 Mtr Long	JAJ A05	Good Working Order	<i>Bes Beqa</i>	No Action Required
Yellow Step Ladder – 2.25 Mtr Long	K 57	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Hop Up - 500 mm Height	THME 01T	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Hop Up - 500 mm Height	Bruka – 0H2	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Hop Up - 500 mm Height	Bruka – 0H3	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Hop Up - 500 mm Height	4412	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Hop Up - 500 mm Height	4413	Good Working Order	<i>Bes Beqa</i>	No Action Required

## Working Platforms, Fall Prevention, Arrest Systems and Ladder Inspection

The Work at Height Regulations 2005	
Report of result of inspection (Regulation 12 (4)(a)(b)) of WORKING PLATFORMS (or part thereof) or of other FALL PREVENTION & ARREST SYSTEMS (including equipment and materials, if any) or of LADDERS as required by Regulation 12 of the Work at Height Regulations	
Note:	1. Where necessary the manufacturer's instruction or other available information should be consulted. 2. Inspection periods must not exceed 7 days 3. Company owned, hired and equipment belonging to employees / subcontractors must be recorded on this form.

<b>Contract Name</b>	30 – 32 Staines Road, Hounslow	<b>Person Carrying out the Inspection</b>	Bes Beqa
<b>Date of Inspection</b>	21 / 10 / 2019	<b>Time of Inspection</b>	09.00

Location and Description of Equipment	Unique Reference Number	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
2.5 Sections Single Tower – 210cm x 180cm x 90cm	JAJ 74	Good Working Order	<i>Bes Beqa</i>	No Action Required
2.5 Sections Single Tower – 210cm x 180cm x 90cm	N / A	Good Working Order	<i>Bes Beqa</i>	No Action Required
2.5 Sections Single Tower – 210cm x 180cm x 90cm	N / A	Good Working Order	<i>Bes Beqa</i>	No Action Required
2.5 Sections Single Tower – 200cm x 180cm x 150cm	N / A	Good Working Order	<i>Bes Beqa</i>	No Action Required
2.5 Sections Single Tower – 200cm x 180cm x 150cm	N / A	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Podium – 1.5 Mtr x 60cm x 70 cm	Adi 10	Good Working Order	<i>Bes Beqa</i>	No Action Required
Silver Podium – 1.5 Mtr x 60cm x 70 cm	THME P007	Good Working Order	<i>Bes Beqa</i>	No Action Required