

## Fire Point Inspection Register

<b>Contract</b>	30 – 32 Staines Road Hounslow	<b>Date of inspection</b>	23 / 10 / 2019	<b>Name and position of person making</b>	Bes Beqa
-----------------	----------------------------------	---------------------------	----------------	---	----------

Fire Point Location / Reference	Details of Matter Identified	Action Taken
Block A – Battery Charging Station (Ground Floor)	Good Working Order	No Action Required
Block A – New Canteen / Ground Floor - Gym Area	Good Working Order	No Action Required
Block A – New Changing Room - Gym Area	Good Working Order	No Action Required
Block A – Ground Floor Corridor (Main Entrance Door)	Good Working Order	No Action Required
Block A – Level 1 (Stair Case)	Good Working Order	No Action Required
Block A – Level 2 (Stair Case)	Good Working Order	No Action Required
Block A – Level 3 (Stair Case)	Good Working Order	No Action Required
Block A – Level 4 (Stair Case)	Good Working Order	No Action Required
Block A – Level 5 (Stair Case)	Good Working Order	No Action Required
Block A – Level 6 (Front of Stair Case)	Good Working Order	No Action Required
Block B – Smoking Area – Carpark Area	Good Working Order	No Action Required
Block B – Level 1 (Stair Case)	Good Working Order	No Action Required
Block B – Level 2 (Stair Case)	Good Working Order	No Action Required
Block B – Level 3 (Stair Case)	Good Working Order	No Action Required
Block B – Level 4 (Stair Case)	The Water Extinguisher is Empty and CO2 Extinguisher is Very Dirty	Replaced the Water Extinguisher Immediately as Required and Cleaned Up the Existing CO2 Extinguisher