










## Working Platforms, Fall Prevention, Arrest Systems and Ladder Inspection

### The Work at Height Regulations 2005

Report of result of inspection (Regulation 12 (4)(a)(b)) of WORKING PLATFORMS (or part thereof) or of other FALL PREVENTION & ARREST SYSTEMS (including equipment and materials, if any) or of LADDERS as required by Regulation 12 of the Work at Height Regulations

- Note:
1. Where necessary the manufacturer's instruction or other available information should be consulted.
  2. Inspection periods must not exceed 7 days
  3. Company owned, hired and equipment belonging to employees / subcontractors must be recorded on this form.

<b>Contract Name</b>	30 – 32 Staines Road, Hounslow	<b>Person Carrying out the Inspection</b>	Ben Hazelden
<b>Date of Inspection</b>	25 / 03 / 2019	<b>Time of Inspection</b>	15.30

Location and Description of Equipment	Unique Reference Number	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
Hop Up - Silver	H 002	Good Working Order		No Action Required
Hop Up - Silver	H 003	Good Working Order		No Action Required
Hop Up - Silver	H 004	Good Working Order		No Action Required
Step Ladder - Yellow	S 0001	Good Working Order		No Action Required
Step Ladder - Yellow	S 0003	Good Working Order		No Action Required
Step Ladder - Yellow	S 0004	Good Working Order		No Action Required
Step Ladder - Yellow	S 0005	Good Working Order		No Action Required
Step Ladder - Yellow	S 0006	Good Working Order		No Action Required
Step Ladder - Silver	S 0020	Good Working Order		No Action Required












## Working Platforms, Fall Prevention, Arrest Systems and Ladder Inspection

### The Work at Height Regulations 2005

Report of result of inspection (Regulation 12 (4)(a)(b)) of WORKING PLATFORMS (or part thereof) or of other FALL PREVENTION & ARREST SYSTEMS (including equipment and materials, if any) or of LADDERS as required by Regulation 12 of the Work at Height Regulations

- Note:
1. Where necessary the manufacturer's instruction or other available information should be consulted.
  2. Inspection periods must not exceed 7 days
  3. Company owned, hired and equipment belonging to employees / subcontractors must be recorded on this form.

<b>Contract Name</b>	30 – 32 Staines Road, Hounslow	<b>Person Carrying out the Inspection</b>	Ben Hazelden
<b>Date of Inspection</b>	25 / 03 / 2019	<b>Time of Inspection</b>	15.30

Location and Description of Equipment	Unique Reference Number	Result of Inspection	Signature of Person Carrying out the Inspection	Action Taken / Date
Orange Ladder – 5 Mtr Long	L 01	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 04	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 05	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 06	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 07	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 08	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 09	Good Working Order		No Action Required
Orange Ladder – 5 Mtr Long	L 10	Good Working Order		No Action Required
Orange Ladder – 4 Mtr Long	OL 20	Good Working Order		No Action Required
Orange Ladder – 4 Mtr Long	OL 21	Good Working Order		No Action Required
Orange Ladder – 4 Mtr Long	OL 22	Good Working Order		No Action Required
Orange Ladder – 4 Mtr Long	OL 23	Good Working Order		No Action Required